



U.S. Department  
of  
Transportation  
**Federal Motor  
Carrier Safety  
Administration**

1200 New Jersey Ave., S.E.  
Washington, DC 20590

July 22, 2010

In reply refer to:  
Your USDOT No.: 329494  
Review No.: 810491/CR

ROBERT BURGMEIER  
PRESIDENT  
HOT LINE FREIGHT SYSTEM INC  
W2197 CTY ROAD B  
WEST SALEM, WI 54669

Dear ROBERT BURGMEIER:

The motor carrier safety rating for your company is:

**SATISFACTORY**

This **SATISFACTORY** rating is the result of a review and evaluation of your safety fitness completed on July 20, 2010. A **SATISFACTORY** rating indicates that your company has adequate safety management controls in place to meet the safety fitness standard prescribed in 49 C.F.R. 385.5.

Please assure yourself that any specific deficiencies identified in the review report have been corrected. We appreciate your efforts toward promoting motor carrier safety throughout your company. If you have questions or require further information, please contact:

U.S. DEPARTMENT OF TRANSPORTATION  
FEDERAL MOTOR CARRIER SAFETY ADMINISTRATION  
1 POINT PLACE, SUITE 101  
MADISON, WI 535282809  
Telephone No.: 608-662-2010

John Van Steenburg  
Director, Office of Enforcement and  
Compliance